

# Carbide Slitting Saws (FP - Fine Pitch) / (CP - Coarse Pitch)



MATERIAL GROUP	MATERIAL TO BE MACHINED	Feed Per Tooth (fz)					
		CARBIDE Vc [m/min]	Ø15-30	Ø30-50	Ø50-80	Ø80-125	Ø125-160
<b>P</b>	Unalloyed steel / Low alloyed steel	80 - 140	0.002 - 0.004	0.003 - 0.007	0.004 - 0.008	0.004 - 0.012	0.004 - 0.012
	Unalloyed steel / Low alloyed steel	50 - 80	0.001 - 0.004	0.002 - 0.005	0.002 - 0.008	0.003 - 0.012	0.003 - 0.012
	Lead alloyed cutting steel	120 - 160	0.003 - 0.007	0.004 - 0.008	0.005 - 0.010	0.005 - 0.010	0.005 - 0.012
	High alloyed steel	50 - 80	0.001 - 0.004	0.002 - 0.005	0.002 - 0.008	0.003 - 0.012	0.003 - 0.012
<b>M</b>	Stainless steel	80 - 120	0.001 - 0.004	0.002 - 0.005	0.002 - 0.008	0.003 - 0.012	0.003 - 0.012
	DUPLEX stainless steel	50 - 80	0.001 - 0.004	0.002 - 0.005	0.002 - 0.008	0.003 - 0.012	0.003 - 0.012
<b>K</b>	Grey cast iron / Nodular pearlitic iron	80 - 140	0.002 - 0.004	0.003 - 0.007	0.004 - 0.01	0.004 - 0.01	0.004 - 0.01
	Alloyed cast iron / Nodular pearlitic iron	50 - 80	0.001 - 0.004	0.002 - 0.005	0.002 - 0.008	0.003 - 0.012	0.003 - 0.012
	Nodular ferritic cast iron / Malleable cast iron	50 - 80	0.002 - 0.004	0.003 - 0.007	0.004 - 0.01	0.004 - 0.01	0.004 - 0.01
<b>S</b>	Special alloys / Heat resistant stainless steel	20 - 30	0.001 - 0.004	0.002 - 0.005	0.002 - 0.008	0.003 - 0.012	0.003 - 0.012
	Titanium, Titanium alloys	30 - 70	0.001 - 0.004	0.002 - 0.005	0.002 - 0.008	0.003 - 0.012	0.003 - 0.012
<b>N</b>	Copper alloys - Easy to machine (Brass - Bronze)	200 - 450	0.003 - 0.007	0.004 - 0.008	0.005 - 0.010	0.005 - 0.010	0.005 - 0.012
	Copper alloys - Difficult to machine / Aluminium bronze	150 - 300	0.001 - 0.004	0.002 - 0.005	0.002 - 0.008	0.003 - 0.012	0.003 - 0.012
	Aluminium alloys	200 - 500	0.003 - 0.007	0.004 - 0.008	0.005 - 0.010	0.005 - 0.010	0.005 - 0.012
	Cast aluminium	200 - 450	0.003 - 0.007	0.004 - 0.008	0.005 - 0.010	0.005 - 0.010	0.005 - 0.012
	Plastic	130 - 200	0.003 - 0.010	0.004 - 0.010	0.005 - 0.012	0.005 - 0.012	0.005 - 0.015
	Gold, Silver	140 - 180	0.003 - 0.007	0.004 - 0.008	0.005 - 0.010	0.005 - 0.010	0.005 - 0.012

Key	
Vc	Cutting speed (m/min)
n	RPM (rev/min)
Fz	Feed rate (mm/tooth)
f	Feed rate (mm/rev)
z	No. of teeth

To calculate RPM from cutting speed: 
$$n = \frac{v_c \cdot 1000}{\pi \cdot \phi}$$

To calculate cutting speed from RPM: 
$$v_c = \frac{n \cdot \pi \cdot \phi}{1000}$$

All recommendations are based on ideal machining conditions. Adjustments may need to be made according to your set-up. The recommendations for speeds, feeds and other parameters presented in this chart are nominal recommendations and should be considered only as good starting points.